


➔ **DOMETIC**

NRX0090V





12/24 V


R600a




DIMENSIONS




**Absorber
MDC90**






NRX0090V






NRX0090V







! DANGER



NOTICE




NOTICE





AIR FLOW

Insufficient air flow results in shortened lifespan and reduced cooling performance. Observe the minimum spacings when installing the refrigerator to furniture.


A





B




CONDENSATION DRAIN




DC







FIXING



FIXING



REVERSING DOOR



DOMETIC

YOUR LOCAL DEALER
dometic.com/dealer

YOUR LOCAL SUPPORT
dometic.com/contact

YOUR LOCAL SALES OFFICE
dometic.com/sales-offices

A complete list of Dometic companies, which comprise the Dometic Group, can be found in the public filings of:
DOMETIC GROUP AB Hemvärmgatan 15 SE-17154 Solna Sweden